

GOLD STANDARD INSTALLATION


THE CINDERELLA COMFORT

Over 70% of toilet issues are the direct result of faulty installation


Faults caused by a faulty installation are not covered by the 3 year warranty.

See detailed instruction manual enclosed.

Contact us before you make an installation outside of these guidelines.



SEEN FROM FRONT



SEEN FROM SIDE

